

Photographs taken by Zoe Linton during site visit 7<sup>th</sup> November 2023




Air con attached to rear of outbuilding Anchor Paddock



Air con on side of White Barn




Building in the North West Corner



Drive dividing in two looking NE



Driveway and view North



Driveway looking NE



Eastern corner of White Barn with Balcony above



Eastern elevation looking NW





Eastern elevation with 1st floor extension



End of first floor wrap around extension looking S



Entry door bells



Fence line from drive looking SE



First floor East Elevation



From Drive looking NE greenhouse in distance



Front Door White Barn



View of pool & greenhouse






Garage without garage door




Gateway to White Barn on right and tree house on left



Inside outbuildings to the West (office)



Inside part finished outbuilding on West




NE view of White Barn garage parking in foreground



North elevation showing roof & retaining walls



Northern elevation



Office internal photo reflection of white barn





Outbuildings behind garage to the West



Parking area to the front of White barn looking South



Part built garage and rear of outbuilding anchor paddock